



LOG FOR NOVEMBER 12, 2020

THE INFORMATION HEREIN CONTAINED IS SOLELY FURNISHED FOR THE USE OF APCO MEMBERS. ANY OTHER USE MAY CONSTITUTE COPYRIGHT INFRINGEMENT.

Actions taken from October 22, 2020 to current.

| ITEM | COORD | STATUS | AGENCY | TX CITY | FREQUENCY/STN CLASS/ERP/ELEVATIONS AND REMARKS |
|------|--------|--------|-----------------------------------|--------------------------|--|
| 1 | 400562 | APPD | PORTERVILLE CITY OF | PORTERVILLE (PD) | A 155.100 155.085 156.000 154.280 FB FBS FX1 200 W ERP -27 AAT 140 MSL 18 AGL PW IMSA EXISTING SYSTEM NEW SITE |
| 2 | 400802 | APPD | BELVEDERE CITY OF | BELVEDERE | A 453/458.100 FB2T MO 25 W ERP PW FCCA TEMPORARY SYSTEM FOR PW |
| 3 | 254135 | APPD | MADERA CO SHERIFF | BASS LAKE (GOAT MTN) | A 151.0125 FB2 45 W ERP 364 AAT 1517 MSL 9 AGL PW APCO ADDING SITE NEW OUTPUT USING EXISTING SYS INPUT FREQ |
| 4 | 254179 | PEND | NORTH CENTRAL FIRE PROT DIST | TRANQUILITY KERMAN BIOLA | A 154.8975 FB FB2 MO 110 W ERP 44 AAT 77 MSL 43 AGL PW APCO NCFPD SEPERATING FROM FRESNO DISP NEEDING NEW SYS |
| 5 | 400813 | APPD | REDWOOD VALLEY CALPELLA FIRE DIST | REDWOOD VALLEY | A 453.050 FB MO 45 W ERP -228 AAT 220 MSL 6 AGL PW FCCA |
| 6 | 200554 | APPD | CALIFORNIA STATE OF (DOT) | BUTTE MEADOWS WESTWOOD | A 460/465.1125 460/465.2875 FXO 64 W ERP 850 AAT 2204 MSL 8 AGL PW AASHTO |
| 7 | | | | | |
| 8 | | | | | |
| 9 | | | | | |
| 10 | | | | | |
| 11 | | | | | |
| 12 | | | | | |
| 13 | | | | | |
| 14 | | | | | |
| 15 | | | | | |
| 16 | | | | | |
| 17 | | | | | |
| 18 | | | | | |
| 19 | | | | | |
| 20 | | | | | |

800 MHz PUBLIC SAFETY (GE, GP, YP, GF, YF) & CommI Users

| | | | | | |
|----|--|--|--|--|--|
| 21 | | | | | |
| 22 | | | | | |

ALL ELEVATIONS SHOWN ARE IN METERS.

Use of lower case indicates an informal action. Contact one of the advisors immediately if such action would impact your system.
 Blue - Carried over from prior month. Black - Added up to meeting date. A= ADD FREQ, D=DELETE FREQ, M=MODIFICATION
 Entries in italics are applications from other coordinators and not in the APCO standard numbering sequence.